

# A WIN-WIN DEAL

## MODEL 7010

### PORTABLE INSTRUMENT LANDING SYSTEM RECEIVER (PIR)

#### PART NUMBERS 098588-0202 AND 098588-0300 (ONLY)



The most versatile PIR in the world just got better. Thales ATM now has available a software upgrade for the Model 7010 PIR that allows calibration only once every 4 years, instead of the present 1-year cycle. The USA Federal Aviation Administration (FAA) for PIR part numbers 098588-0202 and 098588-0300 has approved this 4-year calibration cycle. These units have been incorporated into the FAA's ILS Maintenance Manual.

### Savings and Convenience

For just \$1,200.00 you can upgrade the software to your PIR. See the following cost savings:

- Calibrations for 4 years ( $\$265 \times 4 = \$1,060$ ). (Cost subject to change).
- Shipping charges for 4 years ( $\$35 \times 4 = \$140$ ). (Shipping and insurance cost vary).
- PIR calibration downtime for 4 years ( $30 \times 4 = 120$  days Domestic) ( $90 \times 4 = 360$  days International). (Typical).
- Customs duty charges for 4 years. (International customers).

When the 4-year PIR calibration upgrade is purchased this will also incorporate all of the latest software improvements including (Y2K). Units received that do not work or are damaged are subject to additional repair costs.

This upgrade will eliminate the **CAL DUE** indication on the LCD display. **CAL DUE** will be replaced with a 4-year calibration sticker affixed to the front panel.

How long does it take you to get your PIR packed, the paper work filled out and get it shipped? Plus don't forget all the time it takes to keep track of those air bill numbers and the insurance paper work. What if you need your PIR to get the system back on the air and it's being calibrated? With the 4-year software upgrade your PIR is only unavailable once every 4 years. By taking advantage of the 4-year calibration upgrade you will notice the savings immediately of this **Win-Win deal**.

How can you tell if your PIR qualifies for the 4-year calibration software or if the software has already been installed? There are two ways:

1. Check the serial plate on the front of the unit. If the nameplate has part number **098588 or 098588-0300 with serial numbers 001-601 or 1001-1080 or 098588-0202 all serial numbers**, it qualifies for the 4-year calibration upgrade. Next, check the software version. Turn the unit on and press the <SPL> key. Enter the number <500>. Press the <SET> key. If the number on the LCD display is less than 4.0, your system does not have the 4-year PIR Calibration Software. Press the <SPL> key to exit. Turn the unit off.
2. Check the calibration sticker. The 4-year is blue and white.

If you have additional questions, need current pricing, or need a material return authorization number please get in touch with our Domestic Customer Service Department or our International Customer Service Department. **Indicate you would like the PIR Win-Win deal.** If you prefer, you can email us at [pir@us.thalesatm.com](mailto:pir@us.thalesatm.com).

#### Domestic customers

TEL 800-526-3433

TEL 913-422-2600 ext. 5556

#### International customers

TEL 11-1-913 422-2600 ext. 5470

FAX 11-1-913 422-2910

**NOTE:** When returning your PIR for calibration, please return only the PIR (small blue box) with the battery removed. Also, please do not send back the Accessory Kit (suitcase size box) or any of the antennas.



THALES ATM